DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES Office of Structural Materials Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 1.28

WELDING INSPECTION REPORT

Resident Engineer: Casey, William **Report No:** WIR-029847 Address: 333 Burma Road **Date Inspected:** 15-Jul-2013

City: Oakland, CA 94607

Project Name: SAS Superstructure **OSM Arrival Time:** 730 **OSM Departure Time:** 1600 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: **USA Hoist Location:** Crest Hill, IL.

CWI Name: CWI Present: Yes No None present this day **Inspected CWI report:** Yes **Rod Oven in Use:** Yes No No N/A N/A **Electrode to specification:** Yes No N/A Weld Procedures Followed: Yes No N/A N/A **Qualified Welders:** Yes No **Verified Joint Fit-up:** Yes No N/A N/A Yes N/A **Approved Drawings:** Yes No **Approved WPS:** No Yes No N/A **Delayed / Cancelled:**

34-0006 **Bridge No: Component:** Tower Elevator items

Summary of Items Observed:

This Quality Assurance Inspector (QAI) arrived at the USA Hoist production facility for the purpose of performing inspections of Tower Elevator items to the requirements CC0-085, Standard Specification and Special Provisions.

The welding was performed and completed this day of 1/2" longitudinal stiffeners and of 3/8" radial gusset stiffeners for the Safety Mounting Plate per drawing 916250-11. The welding was performed by Manola Lunas #B utilizing Kobe Steel brand 'Familiarc' E71T-1M .045" diameter FCAW-G electrode as per AWS A5.20, D1.1 and the approved WPS# FCAW3210. The shielding gas used was a mix of Argon 75%/CO2 25% with a flow rate of 38CFH. The welds performed of these completed members appear to meet the requirements of the contract documents.

This QAI received the C.O.C.s for Bearing & Roller Mounting Plates (4 total) and Tower Masts #48-51 (4LH/4RH, 8pcs. total) from Tim Moran, with QC welding inspection reports attached. A verification inspection was performed of the members and they appeared to meet the requirements of the contract documents. Green-Tag packages Lots #B360-015-13 and #B360-016-13 respectively, were generated and attached to each load for release.

WELDING INSPECTION REPORT

(Continued Page 2 of 3)













Summary of Conversations:

This QAI informed Tim Moran that above-mentioned items were Green-Tagged and ready to ship.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Gary Thomas (916) 764-6027, who represents the Office of Structural Materials for your project.

WELDING INSPECTION REPORT

(Continued Page 3 of 3)

Inspected By: Morris, Monty Quality Assurance Inspector **Reviewed By:** Foerder, Mike QA Reviewer